

VIN: SALLMAMH3CA383658 Vehicle scanned on 2020/06/25 13:29:00 Using IIDTool BT V3.0 B2624

AAM-Audio Amplifier (Latest Version) Assembly (F113) AH42-19C164-AK -> AH42-18C808-AK Calibration (F124) AH42-14C527-AF = Up-to-date Hardware (F111) AH42-14C524-AF = AH42-14C524-AE = Up-to-date Serial 00C0058995 Strategy (F188) AH42-14C526-AJ = Up-to-date

ABS-Brake Module (Update available – Gap advised bug – it is latest version) Assembly (F113) **Unknown** -> AH42-18C808-AK Calibration (F124) **Unknown** -> AH42-14C527-AF Strategy (F188) **Unknown** -> AH42-14C526-AJ Serial 1112241MO0290 VIN SALLMAMH3CA383658

ACM-Audio System (Latest Version) Assembly (F113) BH42-18C815-AD = Up-to-date Calibration (F126) HTFB Hardware (F111) AH42-14C230-AC = AH42-14C230-AB = Up-to-date Serial 1203467150000000 Strategy (F188) BH42-14C044-AD = Up-to-date VIN SALLMAMH3CA383658

ADCM-Active Damping (Latest Version) Assembly (F113) AH42-18B008-AH = Up-to-date Hardware (F111) 8W83-14C540-AB = Up-to-date Serial 006000173250 Strategy (F188) AH42-14C542-AH = Up-to-date VIN SALLMAMH3CA383658

APIM-Acc. Interface (Latest Version) Assembly (F113) AH42-18C941-AG = Up-to-date Calibration (F124) AH42-14D206-AA = Up-to-date Hardware (F191) AH42-14D203-AA = Up-to-date Serial 0000C5296044 Strategy (F188) AH42-14D205-AL = Up-to-date

ATCM-Terrain Response (Latest Version) Assembly (F113) BH42-14B596-AE = Up-to-date Hardware (F111) BH42-14D022-AB = BH42-14D022-AA = Up-to-date Serial 12W04 Signal (F120) AH42-14D023-AA = Up-to-date Strategy (F188) BH42-14D024-AB = Up-to-date

BCM-Body Control (Latest Version) Assembly (F113) BH42-14F041-AA -> BH42-14B476-AC Calibration (F124) BH42-14C185-AA = Up-to-date Hardware (F111) AH42-14C256-AD = AH42-14C256-AC = Up-to-date Serial 5370131405 Signal (F108) **BH42-14C408-AA** = Up-to-date Strategy (F188) **BH42-14C184-AD** = Up-to-date VIN SALLMAMH3CA383658

CCM-Cruise Control (Latest Version) Assembly (F112) BH32-9G768-AD = Up-to-date Assembly (F113) CX23-9G768-AD -> BH32-9G768-AD Hardware (F111) BW83-14D047-AA = Up-to-date Serial 5612112760037 Signal (F108) BH32-14D048-AA = Up-to-date Signal (F120) BH32-14D049-BC = Up-to-date Strategy (F188) BH32-14D049-AD = Up-to-date VIN SALLMAMH3CA383658

DABM-Digital Radio (Update available) Assembly (F112) AH42-18D493-AB = Up-to-date Hardware (F111) AH42-14D517-AA = Up-to-date Serial 2120321030749 Signal (F120) AH42-14D518-AA -> None Strategy (F188) AH42-14D519-AB = Up-to-date VIN SALLMAMH3CA383658

DCSM - Drivers Clim Seat (Update available) Assembly (F113) AW93-14B663-AD -> AW93-14F268-AE Calibration (F124) AW93-14C145-CA = Up-to-date Hardware (F111) AW93-14C255-AA = Up-to-date Serial 6MLEU Signal (F120) AW93-14C412-AA -> None Strategy (F188) AW93-14C144-AE = Up-to-date

DDM-Driver Door (Update available) Assembly (F112) Unknown -> BH42-14B531-AE Assembly (F113) BH42-14D618-AA -> None Calibration (F124) BH42-14C065-AB -> BJ32-14C065-AC Hardware (F191) BH42-14C235-AA = Up-to-date Serial 230212181636 Signal (F120) BH42-14C321-AA = Up-to-date Strategy (F122) BH42-14C068-AA -> BJ32-14C068-AD Strategy (F188) BH42-14C064-AA -> BJ32-14C064-AD VIN SALLMAMH3CA383658

DSM-Driver Seat (Latest Version) Assembly (F113) AH42-14D600-CE -> AH42-14C708-DE Hardware (F111) 8W83-14C249-BA = Up-to-date Serial 7030286146 Signal (F120) AH42-14C413-BB = Up-to-date Strategy (F188) AH42-14C030-CE = Up-to-date VIN SALLMAMH3CA383658

FEM-Navigation (Latest Version) Assembly (F112) Unknown -> **BH42-10E887-TG** Hardware (F111) AH42-14C233-DB = AH42-14C233-DA = Up-to-date Serial 112152007000 Strategy (F188) BH42-14C056-KE = Up-to-date

GSM-Gear Shift (Update available) Assembly (F113) BH42-7E453-AH -> BH42-7E453-AL Hardware (F111) BH42-14C559-AE = BH42-14C559-AD = Up-to-date Serial 0909111843400000 Signal (F120) BH42-14C560-AA = Up-to-date Strategy (F188) BH42-14C561-AD -> BH42-14C561-AG

HCM-Headlamp (Update available) Assembly (F113) 9X23-13K031-AD -> 9X23-13K031-AE Hardware (F111) 9X23-14C243-AA = Up-to-date Serial 0075-451068 Strategy (F188) 9X23-14C084-AD -> CX23-14C084-AE VIN SALLMAMH3CA383658

HCMB-Headlamp (Latest Version) Assembly (F113) AH42-14F373-AE -> AH42-14F448-AC Calibration (F124) AH42-14D197-AE = Up-to-date Hardware (F111) AH42-14F109-AB = AH42-14F109-AA = Up-to-date Serial 120530080 Signal (F108) AH42-14D195-AC = Up-to-date Strategy (F188) AH42-14D196-AF = Up-to-date VIN SALLMAMH3CA383658

HVAC-Ventilation (Newer than reflash database) Assembly (F112) BH42-18C612-BC -> BH42-18C612-BJ Assembly (F113) BH42-18D679-BC -> None Calibration (F124) BH42-18D620-DE -> BH42-18D620-AF Hardware (F111) BH42-14C239-BA = Up-to-date Serial ' Signal (F120) BH42-14C416-AA -> None Strategy (F188) BH42-18D619-AF = Up-to-date VIN SALLMAMH3CA383658

IPC-Instrument Pack (Update available – probably incorrect) Assembly (F113) AH42-10849-AS = Up-to-date Calibration (F124) AH42-14C088-AN = Up-to-date Calibration (F125) AH42-14C088-BJ = Up-to-date Calibration (F126) AH42-14C088-XH11 -> **None** Hardware (F111) AH42-14C226-AF = AH42-14C226-AE = Up-to-date Serial MSS2S112S Signal (F108) AH42-14C318-AD -> **None** Signal (F120) AH42-14C026-BJ = Up-to-date Strategy (F188) AH42-14C026-AN = Up-to-date VIN SALLMAMH3CA383658

IPMB-Camera (Update available) Assembly (F113) AH42-14F026-AJ -> AH42-19H423-AL Calibration (F124) AH42-14F022-AG = Up-to-date Hardware (F111) AH42-14F015-AC = AH42-14F015-AB = Up-to-date Serial C842700JF0044616 Signal (F108) AH42-14F016-AA = Up-to-date Strategy (F188) AH42-14F017-AM -> AH42-14F017-AN VIN SALLMAMH3CA383658

KVM-Keyless (Latest Version) Assembly (F113) BJ32-19H440-AG -> AH42-19G481-AK Calibration (F124) AH42-14C105-AH = Up-to-date Hardware (F111) BJ32-14C250-AC = Up-to-date Serial 2654577211 Signal (F108) AH42-14C430-AB = Up-to-date Strategy (F188) BJ32-14C104-AE = Up-to-date VIN SALLMAMH3CA383658

PAM-Parking Aid (Latest Version) Assembly (F112) AH42-15K866-BG = Up-to-date Hardware (F111) 6G92-14C244-BF = Up-to-date Serial 120670114600 Signal (F120) AH42-14C377-AC = Up-to-date Strategy (F188) AH42-14C090-AF = Up-to-date

PBM-Parking Brake (Update available) Assembly (F112) AH42-2C496-AF = Up-to-date Hardware (F111) AH42-14C261-AC = AH42-14C261-AB = Up-to-date Serial 000807921322 Strategy (F188) AH42-14C168-AE -> **None** VIN SALLMAMH3CA383658

PCM-Engine TDV8 4.4L (Latest Version) Assembly (F113) **BH42-12A650-NAD -> BH42-12A650-NCK** Calibration (F124) **BH42-12K532-NCK** = Up-to-date Hardware (F111) BH42-12B684-NA = Up-to-date Serial 1254005125031220 Strategy (F188) **BH42-14C204-NTD** = Up-to-date VIN SALLMAMH3CA383658

PDM-Passenger Door (Update available) Assembly (F112) Unknown -> BH42-14B533-AE Assembly (F113) BH42-14D617-AA -> **None** Calibration (F124) BH42-14C109-AB -> BJ32-14C109-AC Hardware (F191) BH42-14C237-AA = Up-to-date Serial 150312034732 Signal (F120) BH42-14C320-AA = Up-to-date Strategy (F122) BH42-14C112-AA -> BJ32-14C112-AD Strategy (F188) BH42-14C108-AA -> BJ32-14C108-AD VIN SALLMAMH3CA383658

RCM-Airbag (Newer than reflash database) Assembly (F112) AH42-14B321-AG = Up-to-date Assembly (F113) AH42-14D374-AF -> AH42-14B321-AG Calibration (F124) BH42-14C098-AA -> AH42-14C098-AB Calibration (F125) AH42-14C098-BD = Up-to-date Hardware (F111) AH42-14C246-AC = AH42-14C246-AB = Up-to-date Serial KKJYA02B51213030 Signal (F120) SRS_L322_10MY_1PPRA1.doc -> None Strategy (F188) AH42-14C028-AE = Up-to-date VIN SALLMAMH3CA383658

RDCM-Rear Differential (Latest Version) Assembly (F113) 9W83-4C016-AD = Up-to-date Hardware (F111) 9W83-14C251-AA = Up-to-date Serial GJ0G42090365 Strategy (F188) 9W83-4C045-AD = Up-to-date VIN SALLMAMH3CA383658

REM-Rear Entertainment (Latest Version) Assembly (F112) AH42-19A164-AD = Up-to-date Hardware (F191) 7H32-14C594-AB = 7H32-14C594-AA = Up-to-date Serial 120554316 Strategy (F188) AH42-14C596-AC = Up-to-date

RLM-Suspension (Update available) Assembly (F113) Unknown -> AH42-19A164-AD Hardware (F111) AH42-14D392-AB = AH42-14D392-AA = Up-to-date Serial 124139295 Strategy (F188) AH42-14D394-AH -> AH42-14C596-AC VIN SALLMAMH3CA383658

SASM-Steering Angle (No update found) Assembly (F113) AH423F818AA Hardware (F111) AH4214C308AA Serial 1-028712 Strategy (F188) VERSION VIN SALLMAMH3CA383658

SRM-Satellite Radio (Latest Version) Assembly (F112) AH22-10D893-EA -> None Assembly (F113) AH42-10F845-AA -> AH42-10D893-DA Calibration (F124) AH42-14C555-DA = Up-to-date Hardware (F191) AH42-14C552-AA = Up-to-date Serial 260001345964 Strategy (F188) AH42-14C554-AA = Up-to-date

TCCM-Transfer Case (Latest Version) Assembly (F113) AH42-7H417-AE = Up-to-date Hardware (F111) AH42-14C365-AC = AH42-14C365-AB = Up-to-date Serial GJ0J46117039 Strategy (F188) AH42-14C366-AE = Up-to-date VIN 856383AC3HMAMLLAS (**NB this is the VIN backwards!**)

TCM-Transmission *6spd s/b 8spd* (Latest Version) Assembly (F112) Unknown -> BH42-7Z369-HK Assembly (F113) BH42-7000-AG -> None Calibration (F124) BH42-7J105-HK = Up-to-date Hardware (F111) BH42-14C247-HB = BH42-14C247-HA = Up-to-date Serial 5801080540159377 Signal (F120) BH42-14C389-HB = Up-to-date Strategy (F188) BH42-7J104-HF = Up-to-date VIN SALLMAMH3CA383658

TEL-Cell Phone (Latest Version) Assembly (F112) AH22-10D893-EA -> None Assembly (F113) AH42-10F845-AA -> AH42-10D893-DA Calibration (F124) AH42-14C555-DA = Up-to-date Hardware (F191) AH42-14C552-AA = Up-to-date Serial 260001345964 Strategy (F188) AH42-14C554-AA = Up-to-date