

Woburn 4x4 Service Centre Ltd
Unit 6, Lower Rectory Farm
Mill Lane
Great Brickhill
Milton Keynes
MK17 9FX
VAT Reg No: 806 5238 36



Invoice

Crystal Motor Company
Rothersthorpe Road
Northampton
NN4 8HZ

Invoice Number: 8959
Invoice Date: 02/08/2021
Account Ref: CRYSTAL

Details

Amount

Investigate DPF-Restricted Performance Faults: Ran Diagnostics & Live Data. EGR Temp Sensor Fault and DPF Soot Accumulation. Smoke Tested Intercooler and Turbo System. Intercooler Pipe/Duct Tubes Leaking, Replace Ducts and Temp Sensor Using Genuine Land Rover Parts. EGR Sensor Thread Damaged on Removal, Repair Damaged Thread. LLR052169 Sensor Exhaust £92.71 LLR056285 Duct-Air £26.13 x2 Carried Out Forced Regeneration on DPF 40 minute Road Test Labour 2.8hrs	346.57
---	--------

VEHICLE: Range Rover	Total Net Amount	346.57
REG: DT09 JUN	Total VAT @ 20%	69.31
CHASSIS: SALLMAMJ3CA382581	Invoice Total	415.88
MILEAGE: 111,812		

For Internet Payment : HSBC Bank PLC Sort Code: 40-33-33 Acc: 11588583. Please quote your surname or vehicle reg. as a reference. Alternatively call the office for card payment. Thank you