


Connector Face

[Click to toggle focus](#)



Housing

Not Serviceable

Engineering Part Number

4R3T-14A464-AB-014

Service Part Number

Colour

BLACK

Cavities

18

Harness


ENGINE COMPARTMENT LH HARNESS

Description

Module-Speed control

Location

Behind center of bumper



Wire chart and service repair kit information

CAV	CSA	COL	CCT	DESTN
1	0.5	BU-GN	GTDAD	C31-L1
3	0.5	BK	GTDAD	G1D129BL
7	0.5	GY-BU	GTDAD	S1DB26A
8	0.5	GN-OG	GTDAD	S1DB25A
10	0.35	WH-VT	GTDAD	C2BP01H